

Design and Fabrication of High Pressure Feed Effluent Heat Exchangers Low Alloy Steel 2 1/4 Cr 1 Mo With Weld Overlay

Fabrication, Technology and Challenges

PIDEMCO

*Petrochemical Industries Design Equip. & Parts Manufacturing Co.
Iran/March 2017*



NO.33 • SANAT YEKOM ST. • ENGHELAB BLVD. • SHAHR E GHODS

20TH KM TEHRAN-KARAJ OLD ROAD • TEHRAN • IRAN

Petrochemical Industries Design Equip. & Parts Manufacturing Co.

به نام خداوند جان و خرد

ما را که درد عشق و بلای خمار هست

یا وصل دوست یا می صافی دوا کند

در اوایل سال ۱۳۹۵ خورشیدی شرکت پیدمکو موفق به اخذ سفارش در خصوص

طراحی و ساخت تعدادی مبدل خاص پوسته و لوله از نوع Effluent Heat

Exchangers از شرکت مهندسی و ساخت نارگان جهت فاز توسعه شرکت پالایش نفت

اصفهان گردید. از آنجاییکه این مبدل ها برای نخستین بار در کشورمان ساخته می شدند و

بار علمی و تجربی خاص و ارزشمندی برای این مجموعه _ شرکت طراحی و ساخت

قطعات و ماشین آلات صنایع پتروشیمی (پیدمکو) به همراه داشتند، بر آن شدیم تا با ثبت و

درج تجربیات گرانقدر حاصل از این پروژه، دستاوردهای خود را به اشتراک بگذاریم.

در این راستا شایسته است از مدیریت و کارشناسان محترم شرکت مهندسی نارگان

بخاطر همکاری های ثمربخش خود بویژه اعتماد ایشان به صنایع داخل کشور سپاس گزاری

نمایم. آنچه بیش از هر چیز دیگر انگیزه خاصی در نگارش این صفحات گردید شاید دقایق

حساس، ظریف و دشواری بود که قدم به قدم در تمامی فرآیندهای تولید این تجهیزات خاص

وشکفت انگیزبا قدرت و سماجت خاصی پنهان گشته بود و روی نمی نمود. تلاش بسیار

گردید تا از تاریکی های نگران کننده آن بسلامت عبور کنیم و در این مسیر خداوند یارویاور

عاشقان حقیقت است.

امیداست نتیجه تلاش های شبانه روزی و دلسوزانه همه کارشناسان صدیق شرکت پیدمکو

بتواند راهنمای کوچکی برای سایر پویندگان این مسیر باشد. مسیر توسعه، پیشرفت و بومی

سازی هر چه بیشتر صنایع سنگین در ایران عزیز.

به امید تحقق آن روز-/ پیدمکو - پاییز ۹۶

سیامک رحیمی

جا دارد از زحمات برادر بزرگوارم جناب آقای مهندس جهدکاران که در نگارش، تنظیم و تدوین این صفحات ما را یاری رسانده و با رهنمودهای صمیمانه خود این مهم را ختم به خیر نمودند سپاسگزاری نموده و از خداوند منان برای ایشان توفيق روزافزون را خواستارم.

س. رحیمی

Contents

Abstract	13
Part I: Engineering Design.....	15
Chapter 1: Material Selection.....	16
1. <i>Base Metal</i>	16
2. <i>Internal Surface and Tube Bundle</i>	20
Chapter 2: Mechanical Design	22
1. <i>Bolted Flange and Gasket Design</i>	23
1-1. Gasket selection	23
1-2. Gasket Width and Design	23
2. <i>Bolt Size and Number</i>	24
3. <i>Bolt Tensioner</i>	24
4. <i>Gasket Seating Surface</i>	25
5. <i>Hydro test and Strength Calculation</i>	25
Chapter 3: Derived Procedures.....	27
1. <i>Scope</i>	27
2. <i>Code and Standard</i>	28
3. <i>Material Inspection</i>	28
4. <i>Marking for Identification & Traceability</i>	29
5. <i>Cutting and Edge Preparation</i>	30
6. <i>Shell Rolling</i>	32
7. <i>Head Forming</i>	34
8. <i>Tube Bundle</i>	36
9. <i>Manufacturing of Parts and Accessories</i>	38
10. <i>Assembly and Fitting of Parts</i>	41
11. <i>Welding</i>	42
12. <i>Non-Destructive Examination (NDE)</i>	50
13. <i>Dehydrogenation Heat Treatment & Intermediate stress Relief</i>	53
14. <i>Tube Expanding</i>	54
15. <i>PWHT / Hardness Test</i>	55
16. <i>Pressure Test</i>	56
17. <i>Surface Preparation & Painting/Glass bead blasting procedure</i>	59
18. <i>N2 Purging Procedure</i>	60
19. <i>Marking</i>	60
20. <i>Shipping</i>	61

<i>21. Heat Exchanger Tolerances</i>	63
<i>22. Derived Procedures List</i>	63
Chapter 4: Open Platform Communication (OPC)	66
<i>1. Control and Monitoring Production</i>	66
<i>2. Modern manufacturing plants Requires Flexible System</i>	66
<i>3. OPC Forms From Shop Floor to Top Floor</i>	66
Part II: Manufacturing	87
Chapter 1: Machining	88
<i>1. Thermal Cutting and Beveling</i>	88
1-1. Thermal Cutting.....	88
1-2. Beveling.....	90
<i>2. Rolling</i>	91
<i>3. Body Flange</i>	92
<i>4. Inlet & outlet RTJ Flanges</i>	93
<i>5. Tube Sheet Preparation</i>	98
Chapter 2: Welding	99
<i>1. Welding challenges</i>	99
<i>2. Providing Welding Process Specification</i>	102
2-1. Purpose	102
2-2. Master List of Material' Welding Map and NDT Table	102
2-3. WPS & PQR.....	107
<i>3. Weld Over Lay Procedure</i>	178
3-1. Scope.....	178
3-2. Preparing for Welding	178
3-3. American Standard And Project References:.....	178
3-4. Cladding Method by Using SMAW &SAW & ESW	178
3-5. PQR Test requirement	183
3-6. Acceptance Criteria for PT	195
3-7. Nondestructive Examinations (NDE)	195
3-8. Reporting.....	198
<i>4. Welding Consumables Requirements</i>	201
4-1. Material Requirements	201
4-2. Mechanical properties	202
4-2-1. <i>Tensile Properties</i>	202
4-2-2. <i>Impact Properties</i>	202
4-2-3. <i>Step Cooling Tests</i>	202
4-2-4. <i>Required Manufacturer Test Certificate</i>	204
<i>5. Welding Repair Procedure</i>	228

5-1. Scope.....	228
5-2. Applicable Code and Reference Document.....	228
5-3. Definition	228
5-4. General Requirements	228
5-5. Repair Procedure for Base Metal	229
5-6. Preparation for Welding	230
5-7. Repair Welding.....	231
5.7.1 <i>Welding Procedure</i>	231
5.7-2. <i>Welding Equipment</i>	232
5.7-3. <i>Alignment Markers</i>	232
5.7-4. <i>Weld Quality</i>	232
5-8. Post Weld Heat Treatment Operation.....	233
5-8-1. <i>Dehydrogenation Heat Treatment</i>	233
5-8-2. <i>Post Weld Heat Treatment</i>	233
5-9. Inspection	234
5-10. Recording	234
Chapter 3: Heat Treatment	236
1. <i>Dehydrogenation & Intermediate Stress Relief Procedure</i>	236
1-1. Scope.....	236
1-2. Applicable Document.....	236
1-3. Preheating	236
1-4. Dehydrogenation Heat Treatment (DHT)	239
1-5. Intermediate Stress Relief (ISR)	242
2. <i>Post Weld Heat Treatment (PWHT)</i>	249
2-1. Scope.....	249
2-2. Terms & Definition.....	249
2-3. References.....	251
2-4. General Notes.....	251
2-5. Temperature and Holding Time.....	252
2-6. Recording.....	257
2-7. Measurement of Temperature in Furnace	257
2-8. Locally Heat Treatment	258
Chapter 4: Hardness Test Procedure.....	260
1. <i>Scope</i>	260
2. <i>Instruction of Hardness Test Ultrasonic Machine</i>	260
3. <i>Hardness Checking</i>	262
4. <i>Hardness Test</i>	263
5. <i>References & Sample Form</i>	264
Chapter 5: Air Leak Test Procedure.....	266
1. <i>Scope</i>	266

2. Application Code & Specification	266
3. Test Procedure	266
4. Repairs	268
5. Document Control.....	268
Chapter 6: Production Test Plate.....	269
1. Scope.....	269
2. Reference	269
3. Test procedure	269
3-1. Location of Test.....	269
3-2. Chemical Composition of production welds	270
3-3. Hardness of Welds Deposit and Adjacent Base metal	270
4. Type of tests	270
5. Weld Impact Test	271
6. Mechanical Test.....	271
7. Rejection	271

Part III: N.D.T & Hydrostatic Test.....273

Chapter 1: Non Destructive Testing	274
1. Radiography Testing Procedure	274
1-1. General Requirement.....	274
1-2. Equipment and Material	274
1-3. Surface Preparation	275
1-4. Identification and Marking of Film	275
1-5. Examination	276
1-6. Radiographic Technique	279
1-7. Inspection.....	281
1-8. Acceptance Criteria.....	282
1-9. Qualification of Personnel	284
1-10. Documentation.....	284
1-11. Film Identification.....	285
2. Ultrasonic Testing Procedure.....	286
2-1. Scope.....	286
2-2. Reference	286
2-3. Personnel Requirement.....	286
2-4. Responsibility.....	287
2-5. General Requirement.....	287
2-6. Equipment.....	287
2-7. Calibration	288
2-8. Examination of Weld	292
2-9. Scanning	293
2-10. Recording.....	294

<i>3. Dye Penetrant Testing</i>	299
3-1. Scope.....	299
3-2. Reference	299
3-3. Responsibility.....	299
3-4. Safety requirement	299
3-5. Equipment.....	300
3-6. Examination	301
3-7. Evaluation of Indication	302
3-8. Personal qualification	304
3-9. Document.....	304
3-10. Acceptance Criteria	304
<i>4. Magnetic Particle testing</i>	306
4-1. Scope.....	306
4-2. Reference and Abbreviation.....	306
4-3. Equipment.....	306
4-4. Surface Condition	307
4-5. Method of Examination	307
4-6. Calibration of Equipment.....	308
4-7. Examination	309
4-8. Evaluation of Indication	311
4-9. Acceptance Criteria.....	312
4-10. Repair	312
4-11. recording	313
Chapter 2: Hydrostatic Test Procedure	315
<i>1. Scope.....</i>	315
<i>2. Definition</i>	315
<i>3. Reference</i>	315
<i>4. General Requirements</i>	315
<i>5. Test Water</i>	316
<i>6. Equipment</i>	316
<i>7. Metal Temperature</i>	318
<i>8. Test Procedure</i>	318
<i>9. Test Sequence.....</i>	319
<i>10. Acceptance Criteria</i>	324
<i>11. Reports</i>	324
Part IV: Finishing and Preservation.....	327
Chapter 1: Finishing and Preservation	328
<i>1. Scope.....</i>	328
<i>2. Definition</i>	328
<i>3. Reference</i>	328

<i>4. General Purpose</i>	328
<i>5. Description of Process</i>	329
<i>6. Storage and Preservation Procedure</i>	330
6-1. General	330
6-2. Storage and Procedure	331
6-3. Vendor's Responsibilities	332
Part V: Loading and Shipping.....	335
Chapter 1: Loading and Shipping.....	336
<i>1. Scope</i>	336
<i>2. General Purpose</i>	336
<i>3. Reference</i>	336
<i>4. General instructions</i>	336
4-1. Limit of dimensions and weight	336
4-2. Materials	337
4-3. Joints	337
4-4. Superimposition load	338
4-5. Documentation	338
4-6. Packer's assistance	338
4-6-1. <i>Piping, Steel Structures should be done with category F</i>	339
4-6-2 <i>Apparatuses should be done with category A:</i>	339
4-6-3 <i>Small-sized Cases - wooden board sheathing</i>	339
4-6-4. <i>Reduced-size Cases (wooden board sheathing)</i>	340
4-6-5. <i>Small-sized Crates</i>	343
4-6-6. <i>Reduced-size Crates</i>	344
4-7. <i>SADDLE</i>	346
4-8. <i>BUNDLE</i>	349
<i>5. Description of Process</i>	350
<i>6. Marking</i>	351
<i>7. Preservation</i>	352
<i>8. Shipping</i>	352
<i>9. Master Packing list</i>	353
<i>10. Single Packing List</i>	354
References	357

Abstract

Diesel is one of the largest contributors to environmental pollution problems worldwide. Recent changes in environmental norms worldwide have forced all major refineries in the world to produce oil with low sulfur level. Thus Heavy Wall Feed Effluent Heat Exchangers are being designed and manufactured as a vital part of DHT plant. They are used to preheat gas oil (Diesel+H₂) in the shell side before entering the reactor preheater furnace and cool the treated feed (Diesel + H₂ +H₂S) in the tube side that is taken from the reactor discharge nozzle. The presence of hydrogen under very high pressure and high temperature creates potential situation for hydrogen disbonding and cracking. A way to protect exchangers from these harmful effects is using 2 ¼ Cr 1 Mo Gr-22 cladded with SS 347 steel plate with special manufacturing technologies.

The complexities of equipment and the design requirements made a number of challenges in design, manufacturing technologies and fabrication methods.

Some of the manufacturing technologies are:

- 1-** Warm rolling plate & self- reinforced nozzle fit up.
- 2-** Robotic internal bore weld overlay cladding and TIP TIG machine for GTAW of self- reinforced nozzles and pipes.
- 3-** Precession beveling of plate edges and nozzle opening area by portable milling machine.
- 4-** Dissimilar metal joining.
- 5-** Development of modular furnace (large capacity furnace) to avoid local heat treatment.
- 6-** Final PWHT and relevant considerations.
- 7-** Various welding and cladding methods and technology SMAW/SAW/GTAW/ESW.
- 8-** Hydro-Tests &clad-passivation of surface with pickling + drying + cleaning and N₂ pressurizing.
- 9-** NDT methods and effectiveness.
- 10-** Seamless dish head hot forming.